







■ Tower

Area Assessment

No Initial Visible Contamination Action Needed

Remediated to Visual Clearance

Not Accessible

RECON PROGRESS AS OF 2/19/2018

Queen Anne Lead Site ecology and environment, inc.

Global Environmental Specialists

Seattle, WA

Date: 2/19/2018